

16/2016
OM07/16

Transport NI
Western Division
County Hall
Drumragh Avenue
Omagh
BT79 7AF

26th February 2016

Dear [REDACTED]

Proposed Abandonment at Mullydoo Road, Greencastle

Thank you for your letter received on 25th February 2016 regarding the above.

I write to advise that Northern Ireland Electricity has no record of any equipment at the above location and therefore have no objection to your proposal.

A copy of our records has been enclosed for your information.

Any further queries should be made in writing to Wayleave Payments at the above address quoting our reference number.

Yours sincerely

[REDACTED]
Department for Regional Development
LANDS SECTION

2 MAR 2016

[REDACTED]
Reports Section, Western Division
County Hall, Drumragh Avenue, Omagh

NIE Networks
Wayleave Payments

Enc

PLEASE INCLUDE OUR REFERENCE ON ALL CORRESPONDENCE



Based upon the Ordnance Survey map with the permission of the director and the chief executive, Crown copyright. ©



Scale : 1:2500

Date : 26/02/2016 09:15:24

Map Centre : 257980.384587

| |
|---------|
| 400 kV |
| 275 kV |
| 110 kV |
| 33 kV |
| 11 kV |
| 6.6 kV |
| 0.4 kV |
| Service |

CAUTION! CABLE POSITIONS ARE APPROXIMATE ONLY.

Please note that smaller service cables may not be shown. Always remember that it is the responsibility of the excavator to locate and avoid damage to N.I.E. equipment. Failure to do so may result in those responsible being held liable.



Drawing No:

Project No:



Based upon the Ordnance Survey map with the permission of the director and the chief executive. Crown copyright. ©

Drawing No:
Project No:

Date : 26/02/2016 09:12:35
Scale : 1:3000
Map Centre : 258986,384431

| | | | |
|-------|--------|--------|---------|
| 400 m | 200 m | 100 m | 50 m |
| 200 m | 100 m | 50 m | 25 m |
| 100 m | 50 m | 25 m | 12.5 m |
| 50 m | 25 m | 12.5 m | 6.25 m |
| 25 m | 12.5 m | 6.25 m | 3.125 m |

CAUTION: CABLE POSITIONS ARE APPROXIMATE ONLY
Please note that smaller service cables may not be shown. Always remember that it is the responsibility of the excavator to locate and avoid damage to N.I.E. equipment. Failure to do so may result in those responsible being held liable.

